Work Order ID 99923

April-16-13 10:24:05 AM

Item ID:

D3166-1

Revision ID:

Item Name:

Basket Hoop

Start Date:

Required Date: 4/30/13

4/16/13

QC:

Start Oty: 45.00

Req'd Qty: 6.00

N900040100

Setup Start

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: 13-04-16 Tooling:

Date: SPC(Y/N):

Date: Date: Run

Stop

Sequence ID/ Work Center ID	Operatior Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp		
Draw Nbr	Revision Nbr											
D3166	Rev A1											
100		,	0.00									
100 Large Fab	Skidtubes	Memo	0.00				5_	SAL	13-0	4-16		
Large Fab	1	Cut 3/4" x 3/4" square tubing 60.00" long.	· .									

110

110 CNC Bend 1

CNC Delta 100 Bender

BENDING MACHINE - SKIDTUBES

Memo

0.00

0.00

Form D3166-1 Basket Hoop as per Dwg D3166 using Bending program 350

BASB, and folio 18.

120

QC6- Inspect dimensions to drawing

0.00

120

Memo

0.00

Quality Control

Inspect Basket Hoop dimensions with template D3166-1-T1 (DT8302)

5 13.04.16

5 SAO 13-04-16



DQA: _____ Date: _____

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

	es / 110				WORK ORDER NOR			TARGE / OI	DA12	QA Closed:	Date	:
Work Orde	r:				DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
Part N					Rework Scrap		1	Skid-tube Machining	Crosstube Small Fab	1	Water Jet d. Eng. Coor.	Engineering Quality
NCR N	0		·		Use-as-is Work Order Update	_	inern	noforming Large Fab	Finishing Composite	Rec/Stol	re/Packaging Supplier	Other
Root				Descri	iption of work order update	1	nitial	Ac	tion	Sign &		
Cause	Date	Step	Qty		or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data												
quip/Tooling			İ			-						
Operator						1						
Material												
Setup] 1									
Other												
Process												
Supplier												
Fraining												
Jnapproved												
						FAUL	T CATE	GORY				
Landin	ıg Gear				General	_					-	_
L	Bending			L	Bend	Ш	Grain			Ovalized		Pressure/Forced
L	Centre No	ot Conce	ntric to (o/s	BOM/Route	Ш	Hardwa	ire		Over/Under	tolerance	Temperature/Cure
L	Cracks				Broken/Damaged		Inspect	ion Incomplete		Part Incorred	ct	Weld
	Crushed/	Crimped		L	Burrs		Instruct	tions Incomplete/	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
.[Cuffs				Contamination		Mainte	enance		Part Moved		
[Heat Trea	at			Countersink		Mislabe	eled		Positioned V	Vrong	
[Inspectio	n Strip in	Tube		Cut Too Short		Misread	b		Power Loss/	Surge	Other
. [Ripples in	Bend			Drill Holes		Offset					
- [Torque W	/aves in E	xtrusion	1 [Drawing		Out of 0	Calibration				
Ţ	Turning S	equence			Finish		Out of	Sequence				
	Wave/Tw	ist in Tul	oe .		Folio		Outside	Dimensions	-			

Work Order ID 99923 *99923*

QC21- Final Inspection - Work Order Release

Memo

April-16-13 10:24:05 AM

140

140 QC

Quality Control

Item ID: D3166-1 Accept *N900040100* Setup Start **Revision ID:** Basket Hoop Item Name: Start Date: 4/16/13 Start Qty: 6.00 Cust Item ID: Required Date: 4/30/13 Req'd Otv: 6.00 **Customer:** Reference: Run Approvals: **Process Plan:** Date: Tooling: Date: QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. Work Center ID Description **Run Hours** Code Qty Qty Number Stamp 130 Identify as per dwg & Stock Location: 0.00 *120* 13-04-16 Packaging Memo 0.00 Packaging

0.00

0.00

DQA: _____ Date: ____

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

							•		QA Closed:	Date:			
Work Orde	or.				DISPOSITION		AGAINST DEPARTMENT/PROCESS						
Part N					Rework Scrap]	Skid-tube Crosstube Machining Small Fab			Water Jet d. Eng. Coor.	Engineering Quality		
NCR No.					Use-as-is Work Order Update	d I ~hi		Finishing Composite	Rec/Sto	re/Packaging Supplier	Other		
Root				Descri	ption of work order update	Initial	Α	ction	Sign &		.:		
Cause	Date	Step	Qty		or Non-conformance	Chief En	g Des	cription	Date	Verification	QC Inspector		
Doc/Data Equip/Tooling Operator Material Setup Other Process													
Supplier Training											,		
Unapproved													
•					F	AULT CAT	EGORY			s			
Landir	ng Gear				General						_		
	Bending Centre No Cracks Crushed/ Cuffs		ntric to (o/s	Bend BOM/Route Broken/Damaged Burrs Contamination	Instru		/Unclear	Ovalized Over/Under Part Incorred Part Lost/Mi Part Moved	ct	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled		
	Heat Trea	••		⊢	Countersink	Misla		 	Positioned V	Vrong			
	Inspectio	n Strip in	Tube		Cut Too Short Drill Holes	Misre	ad		Power Loss/		Other		
	Torque W		xtrusio	,	Drawing	_	f Calibration	•					
	Turning S				Finish	\vdash	f Sequence				· · · · · · · · · · · · · · · · · · ·		
	Wave/Tw	ist in Tul	oe .		Folio	Outsi	de Dimensions	•					

Picklist Print

April-16-13 10:24:10 AM

Work Order ID: 99923

Parent Item:

D3166-1

Parent Item Name: Basket Hoop

99923

D3166-1

Start Date: 4/16/13

Required Date: 4/30/13

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP A02.08.23New issueKJ

IPP: B 08.12.05 Updated bending program on step 3 per NCR W/O43165 KJ

Verified by: EC

IPP Rev:C 09-01-23 as per DEO D3166-A2 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.750W.065 *M304TS0 304 SQ Tube .75x.75x.065W		Purchased 065*	No	· · · · · · · · · · · · · · · ·	· - · · · · · · · · · · · · · · · · · ·	100	f	1,446.172		31.57895 SAD	13-0	4 16	·
				WA006	124069	Loc (436.4 436.4 1009.76	116 116 107	Loc Code	 				
•					124880	60.28 949.4		B	-	31.5.190	- 26 3	150	

~.**,** >

										DQA:	Date	2:
NCR: Y	es / No)			WORK ORDER NON-	CON	FORN	MANCE / UP	DATE	0461	D-4-	
										QA Closed:	Date	2:
Work Orde	or.				DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
WOIR Olde				·	Rework	7 		Skid-tube	Crosstube	1	Water Jet	Engineering
Part N	lo.				Scrap	1		Machining	Small Fab	Pro	d. Eng. Coor.	Quality
rait No.					Use-as-is	1] .		noforming	Finishing	-	e/Packaging	Other
NCR No.					Work Order Update	1		Large Fab	Composite	1 '	Supplier	1
					' <u>-</u>	-				_		
Root				Descri	ption of work order update	lni	itial	Ac	tion	Sign &		
Cause	Date	Step	Qty	<u></u>	or Non-conformance	Chie	f Eng	Desc	cription	Date	Verification	QC Inspector
Doc/Data												
Equip/Tooling		-]		1						
Operator		Ì										
Material							1					
Setup												
Other						1						
Process						1						
Supplier												
Training												
Unapproved										<u> </u>		
 					F	AULT	CATE	GORY				
Landi	ng Gear			_	General					7	-	-
	Bendin	•			Bend	ЩG	Grain		<u> </u>	Ovalized	_	Pressure/Forced
	Centre	Not Conce	ntric to	O/S	BOM/Route	\vdash	lardwa		_	Over/Under	 -	Temperature/Cure
	Cracks				Broken/Damaged	\vdash	-	on Incomplete		Part Incorred)	Weld
	Crushe	d/Crimpec	1		Burrs	Llr	nstruct	ions Incomplete/	/Unclear	Part Lost/Mi	ssing _	Wrong Stock Pulled
	Cuffs				Contamination	\vdash		nance		Part Moved		
	Heat T	reat			Countersink	\mathbf{H}	⁄lislabe			Positioned V		¬
	Inspec	tion Strip ii	1 Tube		Cut Too Short	-	/lisread	ı		Power Loss/	Surge	Other
	Ripples	in Bend			Drill Holes	-	Offset				,	
*	Torque	Waves in	Extrusio	on	Drawing		ot of C	Calibration				
	Turnin	g Sequence	9		Finish		of S	Sequence				
Wave/Twist in Tube				Folio		Outside	Dimensions					

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G






DESIGN	#	DRAWN BY	DART AERO	
CHECK	ED	APPROVED	DRAWING NO.	REV. A
	#	4	D3166	SHEET 1 OF 1
DATE			TITLE	SCALE
02.0	7.10		BASKET HOOP	NTS
A	J	02.07.10	NEW ISSUE	

BELEASE 102.01.06 9

04.04.08 38+1-1 WAS 36.0

DEO ATTACHED




10.6 (REF, NEED 8.0 MIN)

D3166-1 BASKET HOOP

1) MATERIAL: AISI 304/316 SS SQUARE TUBING, 0.75" x 0.75" x 0.063 WALL, 60.00" LONG (REF DART SPEC. M304TS0.750W.063)

2) FINISH: NONE

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED



D3166-3 BASKET HOOP

1) MATERIAL: AISI 304/316 SS SQUARE TUBING, 0.75" x 0.75" x 0.063 WALL, 120.00" LONG (REF DART SPEC. M304TS0.750W.063)

2) FINISH: NONE

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

- [
DRAWING	NO.		E	-		REVA1	DART AEF	30	SPACE LTD	D.E.C	O. NO		SHEET NO.	SCALE
D3166		BAS	KET.HO	DOP			ENGINEE	ŖIJ	NG ORDER	D31	66-A-2		1 OF 1	NTS.
DRAWN	AJS			CHECKED	5		MFG. APPR.	M		APPROV	ED AND	DE AF	PR #	
DATE	08.12.	11	*	DATE 08	2.15		DATE:	x/	12/15	DATE	00/12/16	DATE	08.12.16	
1								~~			0-7-710			

1) MODIFY MATERIAL NOTE FOR D3166-1 AS SHOWN:

IS:

1) MATERIAL: AISI 304/316 SS, 3/4 X 3/4 X 0.065 WALL SQUARE TUBING,

60.00" LONG

REF. DART SPEC M304TS0.750W.065

WAS:

1) MATERIAL: AISI 304/316 SS SQUARE TUBING, 0.75" x 0.75" x 0.063 WALL, 60.00" LONG

(REF DART SPEC. M304TS0.750W.063)

2) MODIFY MATERIAL NOTE FOR D3166-3 AS SHOWN:

IS:

1) MATERIAL: AISI 304/316 SS, 3/4 X 3/4 X 0.065 WALL SQUARE TUBING,

120.00" LONG

REF. DART SPEC M304TS0.750W.065

WAS:

1) MATERIAL: AISI 304/316 SS SQUARE TUBING, 0.75" x 0.75" x 0.063 WALL, 120.00" LONG (REF DART SPEC. M304TS0.750W.063)



REASON: SEE PAR 08-005

USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.